



Figure S1. SEM image of the dentin surface after being demineralized with 37% phosphoric acid for 2 min. Energy disperse spectrum (EDS) (Insets) showed that there were no Ca and P elements on the demineralized surface.