

Supplementary Information

The temperature curves used in the debinding and sintering processes.




Fig. S1 (a) The temperature curve for debinding to obtain the porous glass (b) The temperature curve for sintering the porous silica glass