

Figure S1. (a) Stress-strain curves and (b) ultimate stretching ratio for magnetic hydrogels with different NdFeB concentrations. The curves for 0, 5, 10, and 20 wt% have been shown in Figure 3b.




Figure S2. Stress-strain curves of the pure-shear test for magnetic hydrogels with different microgel content.