



Fig. S1. HRTEM image of two interfaces in the sandwich-like triaxial nanowire between CdSe and Ge subnanowires. Both of the lower CdSe and the upper CdSe section have stacking defects